

87-84 Valentin

Date of issue:

April 29, 1987

Affected motorglider:

German Type Certificate No. 818

Taifun 17 E

all serial numbers

Subject:

1. Rudder pedals, airbrake actuating levers
2. Flightmanual and Instructions for continued airworthiness

Reasons:

Possible damage of controls by overload

Action and compliance:

Action to be accomplished in accordance with Technical Note prior to next flight.

Technical publications of the manufacturer:

Valentin Technical Note No. 11/818 of March 9, 1987

which becomes herewith part of this AD and may be obtained from Messrs. Valentin-Flugzeugbau GmbH, Flugplatzstr. 18, D-8728 Haßfurt, Federal Republic of Germany

Accomplishment and log book entry:

Action step 1 to be accomplished by an approved service station and to be entered in the motorgliders log by a licensed inspector.

Action step 2 to be accomplished by a skilled person and to be entered in the motorgliders log.