

Airworthiness Directive

=====

85-129 Valentin

Date of issue:

June 6, 1985

Affected ~~aircraft~~:

motorglider: Sch 13.2 E

German Type Certificate No. 818

Taifun 17E,

all serial numbers.

Subject:

Improvement of the stall characteristic

Reason:

The stall characteristic can be improved by the reduction of the elevator deflection

Action and compliance:

Action to be accomplished in accordance with Technical Information before July 15, 1985.

Technical publication of the manufacturer:

Valentin Technical Information 4/818 of May 6, 1985 which becomes herewith part of this AD and may be obtained from Messrs. Valentin GmbH, Geräte- und Maschinenbau, Germanenstr. 2, D-8901 Königsbrunn, Federal Republic of Germany.

Accomplishment and log book entry:

Action to be accomplished by an approved service station and to be entered in the motorgliders log by a licensed inspector.