

Airworthiness Directive

85-263 Valentin

Date of issue:

December 12, 1985

Affected motorglider:

German Type Certificate No. 818

Taifun 17E

all serial numbers.

Subject:

stall warning

Reason:

Installation of a stall warning device.

Action and compliance:

Before the next annual inspection, but not later than March 31, 1986
action to be accomplished in accordance with Technical Information.

Technical publication of the manufacturer:

Valentin Technical Information 8/818 of December 10, 1985,
which becomes herewith part of this AD and may be obtained from
Messrs. Valentin Flugzeugbau GmbH, Flugplatzstr. 18, D-8728 Haßfurt,
Federal Republic of Germany.

Accomplishment and log book entry:

Action to be accomplished by an approved service station and to be entered
in the motorgliders log by a licensed inspector.