

AIRWORTHINESS DIRECTIVE

87-135 Valentin

Date of issue:

July 09, 1987

Affected powered Gliders:

German Type Certificate No. 818

Taifun 17 E

all serial numbers

Subject:

C.G. of empty aircraft and in flight, pilot's weight leverarm

Reason:

1. Correction of the permissible C.G. of empty aircraft and pilot's weight leverarm
2. Extension of the permissible range for the C.G. in flight

Action and compliance:

Action to be accomplished in accordance with Technical Note before the next annual inspection, but not later than October 31, 1987.

Technical publication of the manufacturer:

Valentins Technical Note No. 12/818 of April 14, 1987

which becomes herewith part of this AD and may be obtained from Messrs.

Valentin-Flugzeugbau GmbH, Flugplatzstr. 18, D-8728 Haßfurt,

Federal Republik of Germany

Accomplishment and log book entry:

Action to be accomplished by an approved service station and to be entered in the powered gliders log by a licensed inspector.